

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER
COLO
30-LAKWD.V
2B-

GLENN L. MARTIN COMPANY, HAER No. CO-75-B
Titan Missile Test Facilities, Captive Test Stand D-2
Waterton Canyon Road and Colorado Highway 121
Vicinity of Lakewood
Jefferson County
Colorado

Documentation: 13 exterior photographs

Robert Lyon, Photographer, May, July, and August 1993

CO-75-B-1	FLAME DEFLECTOR AT LEFT, COUNTERFORT AT RIGHT, VIEW TOWARDS SOUTH
CO-75-B-2	FLAME DEFLECTOR FROM THE REINFORCED CONCRETE SLAB ROOF, VIEW TOWARDS SOUTHWEST
CO-75-B-3	SOUTH FLAME DEFLECTOR FROM THE REINFORCED CONCRETE ROOF, VIEW TOWARDS WEST <i>East</i>
CO-75-B-4	COUNTERFORT, VIEW TOWARDS NORTHWEST
CO-75-B-5	FLAME DEFLECTOR AT LEFT, FERROCEMENT APRON AT RIGHT CENTER, CONTROL BUILDING A AT FAR RIGHT, CONNECTING TUNNEL AT UPPER CENTER, VIEW TOWARDS NORTHEAST
CO-75-B-6	FLAME DEFLECTOR, VIEW TOWARDS NORTHWEST
CO-75-B-7	FLAME DEFLECTOR, VIEW TOWARDS SOUTHWEST
CO-75-B-8	NORTH FLAME DEFLECTOR, VIEW TOWARDS WEST
CO-75-B-9	FLAME DEFLECTOR, VIEW TOWARDS WEST
CO-75-B-10	REINFORCED CONCRETE SLAB ROOF FROM THE WESTERN EDGE, ACCESS RAMPS AT LEFT AND RIGHT, VIEW TOWARDS EAST
CO-75-B-11	REINFORCED CONCRETE SLAB ROOF FROM THE SOUTHERN EDGE, VIEW TOWARDS NORTH
CO-75-B-12	REINFORCED CONCRETE SLAB ROOF FROM THE NORTHERN EDGE, VIEW TOWARDS SOUTH
CO-75-B-13	REINFORCED CONCRETE SLAB ROOF FROM THE NORTHERN EDGE, VIEW TOWARDS SOUTHWEST